

**Corvallis Natural Features Inventory
Supplemental Riparian Form**

Basin: DIXON	Reach: WC-DIX-R-18-Left	Size: 8.50
Map:		
Dominant Cover Type: WOODY	Matches GIS? TBD	
ARA Type #: Mixed Woodland 30-70% closed canopy		
Other ARA Types: NONE		
% of Total Cover: Trees: 10 Shrubs: 35 Herbs/Vines: 55 Bare: 0		
Dominant Cover Type At Edge of Water: HERBACEOUS		
Edge of Water ARA Type #: Emergent wetland (seasonal)		
Riparian System: LOTIC		
Trees:		
Type: DECIDUOUS		
Dominant Species: Oregon white oak		
Secondary Species: NONE		
% Total Cover: <input type="radio"/> <10% <input checked="" type="radio"/> 10%-50% <input type="radio"/> 50%-90% <input type="radio"/> >90%		
% Invasive Cover: <input checked="" type="radio"/> <10% <input type="radio"/> 10%-50% <input type="radio"/> 50%-90% <input type="radio"/> >90%		
% Native Cover: <input type="radio"/> <10% <input type="radio"/> 10%-50% <input type="radio"/> 50%-90% <input checked="" type="radio"/> >90%		
Shrubs/Sapling		
Type: DECIDUOUS		
Dominant Species: Douglas hawthorn		
Secondary Species: Himalayan blackberry		
% Total Cover: <input checked="" type="radio"/> <10% <input type="radio"/> 10%-50% <input type="radio"/> 50%-90% <input type="radio"/> >90%		
% Invasive Cover: <input type="radio"/> <10% <input checked="" type="radio"/> 10%-50% <input type="radio"/> 50%-90% <input type="radio"/> >90%		
% Native Cover: <input type="radio"/> <10% <input checked="" type="radio"/> 10%-50% <input type="radio"/> 50%-90% <input type="radio"/> >90%		
Herbaceous		
Type: MIXED		
Dominant Species: Meadow foxtail		
Secondary Species: Tall fescue, bentgrass, DIPSACUS SYLVESTRIS, Canada thistle		
% Total Cover: <input type="radio"/> <10% <input type="radio"/> 10%-50% <input checked="" type="radio"/> 50%-90% <input type="radio"/> >90%		
% Invasive Cover: <input type="radio"/> <10% <input checked="" type="radio"/> 10%-50% <input type="radio"/> 50%-90% <input type="radio"/> >90%		
% Native Cover: <input checked="" type="radio"/> <10% <input type="radio"/> 10%-50% <input type="radio"/> 50%-90% <input type="radio"/> >90%		

**Corvallis Natural Features Inventory
Supplemental Riparian Form**

Basin: DIXON

Reach: WC-DIX-R-18-Left

RTE Species

ORNHIC Plant Community: None Noted Listed Community Noted

ORNHIC or Benton Co. NSP List None Detected Potential Listed Species Detected

ORNHIC Association:

Riparian Condition Assessment

Land Use within: COMMERCIAL

Land Use adjacent: COMMERCIAL

Infrastructure Impingement: PARTIALLY IMPINGED

In Channel Alteration: UNALTERED

LWD Recruitment Potential: MODERATE

Shade Potential: LOW

Restoration Potential

Adjacent slopes of 15% or greater <10% 10%-50% 50%-90 >90%

Undeveloped land within 50ft of top of bank <10% 10%-50% 50%-90 >90%

Within 100-yr floodplain: <10% 10%-50% 50%-90 >90%

Low quality wetlands or hydirc soils: <10% 10%-50% 50%-90 >90%

Adjacent landscape areas: <10% 10%-50% 50%-90 >90%

Opportunities: SOME OPPORTUNITY FOR BLACKBERRY REMOVAL AND REPLANT WITH NATIVE TREE AND SHRUBS

Current Efforts NONE OBSERVED

COMMENTS